





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



Position






- 1 = A 962 872 XX
- 3 = A 962 998 NU
- 4 = A 962 870 XX
- 5 = A 962 871 XX
- 6 = A 963 427 NU
- 7 = A 962 229 NU
- 8 = A 962 230 NU
- 9 = A 963 432 NU
- 10 = A 962 563 NU
- 12 = A 962 568 NU
- 14 = A 962 529 NU
- 15 = A 961 332 NU
- 18 = A 962 594 NU
- 19 = A 961 810 NU
- 20 = A 962 595 NU
- 21 = B 960 242 XX
- 22 = A 961 073 XX
- 24 = A 963 651 NU
- 25 = A 960 395 NU
- A 960 196 NU

XX = AA, AD...






CERATHERM 100
A 4623 .. A 4624 ..

0510 / A 866 247
(+ A 865 612)
Made in Germany



Ideal Standard
Roentgenstrasse 9
54516 Wittlich
Germany



	P	bar		MAX. 10		5		Q (3 bar)
	T	°C		MAX. 80		65		l/min
				40		40		20,5

